## LR Field Services

Prepared for PRODUCERS RICE STUTTGART

603 N. PARK AVE STUTTGART AR 72160

## Table of Contents

Field Service Ticket - MOTOR SHOP LR	1.0
Balancing Report - MOTOR SHOP LR	2.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

## **Field Service Ticket**

FolderID: 103682 FormID: 22080105

PRODUCERS RICE STUTTGART

603 N. PARK AVE STUTTGART, AR 72160 MOTOR SHOP LR

Job In	formation			
1.	Hi-Speed Job Number	103682		
2.	Asset Type	fan		
3.	Make	blower # 4		
4.	Model	na		
5.	Serial Number	na		
6.	Customer Asset ID/Asset Name	blower #4		
Service Call Details				
7.	Service Objectives			
	Balance fan			
8.	Services Performed			
	Balanced fan			
9.	Service Technician Recommendations			
	None			
Approval Signatures				
10.	Service Technician Signature	David Maclin		
	M			
11.	Customer Signature	Johnathan Aycock		
	Adda L			

Performed By: Motor Shop LR 1

Date Completed: 10/29/2024



## **Balancing Report**

General

**PRODUCERS RICE STUTTGART** 

603 N. PARK AVE STUTTGART, AR 72160 MOTOR SHOP LR

Performed By: Motor Shop LR 1 Date Completed: 10/29/2024

103682 1. Job Number 2. Report Date 10/29/2024 3. Customer **Producers Rice Balancing Report** 4. Balance Type single plane overhang 5. Balance Operating Speed 2359 RPM 6. Starting Measurements **Right End** Left End 13.3937 3.9073 7. Balancing Specification 1.0 8. Finished Measurements Left End **Right End** 

1.1055 0.05923 9. List Parts Needed 2-29g weights 10. Service Technician **David Maclin** 

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

FolderID: 103682 FormID: 22087886