

ML Field Service

Prepared for AIR TECHNICAL SERVICES INC

3161 STAGE POST DR
BARTLETT TN 38133

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/23/2025

Powered by [INSPECTALL](#)

Table of Contents




Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300


Field Service Ticket

AIR TECHNICAL SERVICES INC
3161 STAGE POST DR
BARTLETT, TN 38133

FolderID: 155627
FormID: 24552866

Job Information

1. Hi-Speed Job Number **155627**
2. Asset Type
 *Air handler joy fan*
3. Make




4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives
Quality check on Joy Fan after motor replacement.
8. Services Performed
Vibration check at max speed 55Hz. All vibration below corrective measure limit.
9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature **Shon Jones**

11. Customer Signature **Daulton Gunn**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

A handwritten signature in black ink, appearing to read "Andrew Davis", is located in the top left corner of the page.