LR Field Services

Prepared for Almatis Inc/RCP Bauxite (10014)

4701 Alcoa Road Bauxite AR 72011

Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

Field Service Ticket

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011 FolderID: 104064 FormID: 23179877

Job Information		
1.	Hi-Speed Job Number	104064
		I50 hp motor and goulds pump
Carrie		
3.	Make	
4.	Model	
5. 6.	Serial Number Customer Asset ID/Asset	
Servic	ce Call Details	
7.		
	To align 150 hp motor to pu	imp.
8.		
		motor to pump. The rear of the motor has no shims under it so I split the difference to get the

Finish

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

11. Customer Signature



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Trevor Hall