LR Field Services

Prepared for Dassault Falcon Jet (11751)

3801 East 10th st. Little rock AR 72203

Table of Contents

Field Service Ticket

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

1.0

2.0



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

Field Service Ticket

Dassault Falcon Jet (11751) 3801 East 10th st. Little rock, AR 72203 FolderID: 104116 FormID: 23547892

	formation	
1.	Hi-Speed Job Number	104116
2.	Asset Type	exhaust fan
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	large exhaust fan
Servic	e Call Details	
7.	Service Objectives	
	To remove stack and fan, replace fan assembly and reinstall the stack.	
8.	Services Performed	
	Customer was not able to shut down and is going to reschedule.	
9.	Service Technician Recommendations	
Appro	val Signatures	
10.	Service Technician Signature	Trevor Hall
11.	Customer Signature	Harrold

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Field Service Ticket

FolderID: 104116 FormID: 24439997

7030 Ryburn Dr

Millington, Tn 38053 901-873-5300

Hi-Speed Industrial Service

Dassault Falcon Jet (11751) 3801 East 10th st. Little rock, AR 72203

Job In	formation	
1.	Hi-Speed Job Number	104116
2.	Asset Type	Exhaust fan
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	Large exhaust fan
Servic	e Call Details	
7.	Service Objectives	
	To remove fan unit and replace with a new one.	
8.	Services Performed	
	We removed the old fan and stack unit and installed a new fan unit.	
	Service Technician Recommendations	
	val Signatures	
10.	Service Technician Signature	Trevor Hall
11.	Customer Signature	Paul Brewer
	Park	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.