

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket
Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

FolderID: 104629
FormID: 24480879

Field Service

Location: LR MOTOR SHOP
Identifier:

Job Information

- | | |
|---------------------------------|---------------------|
| 1. Hi-Speed Job Number | 104629 |
| 2. Asset Type | fan and vacuum pump |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives
To balance 11 dust collector fan and take readings on replacement vacuum pump.
8. Services Performed
Balanced fan from 2 mils down to under 0.2. Took readings on vacuum pump 2. The amplitude on the pump is very low but it the pump is acting like it has too much water in it causing the motor to burn the belts and the inside of the pump is making almost like a rattling sound or popcorn sound. The belts could be loose also but the customer shut down the pump to try to figure out what's wrong with the incoming water.



9. Service Technician Recommendations

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Zak Creasey

