LR Field Services

Prepared for Asphalt Products (12318-02)

2066 Hwy 53N Gurdon AR 71743

Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



FolderID: 103934

FormID: 22775746

Field Service Ticket

Asphalt Products (12318-02) 2066 Hwy 53N

Gurdon, AR 71743

Job In	formation			
1.	Hi-Speed Job Number			103934
2.	Asset Type			Combustion fan and main ID fan
3.	Make			
4.	Model			
5.	Serial Number			
6.	Customer Asset ID/Ass	et Name		combustion and main ID fans
Servic	e Call Details			
7.	Service Objectives			
	Check balance and bala	nce fans		
8.	Services Performed			
	Same as objective		Acquire Vertex of Data HINDER MUX 15 FHABLED Travel Vertex of Data Data State Data State Data State	
iombus	stion blower	Combustion blower final readings	Combustion blower initial readings	ID fan

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



ID fan. Fan end is 0.4. Gets better the faster it goes. No weight added

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

11. Customer Signature

Trevor Hall

Detrick Baugh

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.