

LR Field Services

Prepared for Catlett- The Tower Building (12792)

323 Center Street
Little Rock AR 72201

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104537
FormID: 24312025


Catlett- The Tower Building (12792)
323 Center Street
Little Rock, AR 72201

Job Information


- | | |
|---------------------------------|-------------------|
| 1. Hi-Speed Job Number | 104537 |
| 2. Asset Type | cooling tower fan |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | main cooling fan |

Service Call Details

7. Service Objectives
To troubleshoot cooling tower fan.
8. Services Performed
Customer replaced rubber grommets and they did not seat properly. The shaft from the motor, drive shaft and gearbox and solid now without the proper spacing between each end of the main drive shaft. This is causing a small amount of resonance/vibration. Customer is going to pull the shaft back off and insert the grommets properly and see if vibration goes away.



Supposed to look like this



Not supposed to look like this

9. Service Technician Recommendations

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Rusty Arnold

