

LR Field Services

Prepared for Central AR Water- Lake Maumelle(10195-08)

10629 Hwy 300
Roland AR 72135

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104993
FormID: 25408751

Central AR Water- Lake Maumelle
(10195-08)

10629 Hwy 300
Roland, AR 72135

Job Information

1. Hi-Speed Job Number
2. Asset Type
3. Make
4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives
8. Services Performed
9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature
11. Customer Signature

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 08/07/2025

Powered by [INSPECTALL](#)

1.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104993
FormID: 25409460



Central AR Water- Lake Maumelle
(10195-08)

10629 Hwy 300
Roland, AR 72135

Job Information

1. Hi-Speed Job Number

104993



2. Asset Type

3. Make

4. Model

5. Serial Number

6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives

PDMA test remaining motors not tested. Provide report.



8. Services Performed

9. Service Technician Recommendations

#4 motor showed a 16% resistance imbalance line to line at the drive. Re-tested at motor leads and 0.7% at motor. Customer to check under ground cable and drive. Surge test was acceptable.

Approval Signatures

10. Service Technician Signature

Shon Jones

11. Customer Signature

Chad Roberts

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

A handwritten signature in black ink, appearing to read 'CHRA', is located in the top left corner of the page.