

# LR Field Services

Prepared for ConAgra (10859-CON)

3100 E. Main St.  
Russellville AR 72801

# Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0















Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

Field Service Ticket

FolderID: 104227  
FormID: 23662063

ConAgra (10859-CON)  
3100 E. Main St.  
Russellville, AR 72801

Job Information	
1. Hi-Speed Job Number	104227
2. Asset Type	AC ammonia compressor motor
3. Make	RAM
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	C5 compressor
Service Call Details	
7. Service Objectives	To remove 1000 hp motor off of the compressor.
8. Services Performed	Same as objective.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Jaron Dejongh



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104227  
FormID: 24593751

**ConAgra (10859-CON)**  
3100 E. Main St.  
Russellville, AR 72801

### Job Information

- |                        |                              |
|------------------------|------------------------------|
| 1. Hi-Speed Job Number | 104227                       |
| 2. Asset Type          | Ram ammonia compressor motor |
| 3. Make                | Ram                          |



- |                                 |                |
|---------------------------------|----------------|
| 4. Model                        |                |
| 5. Serial Number                |                |
| 6. Customer Asset ID/Asset Name | C-5 compressor |


### Service Call Details

7. Service Objectives  
*To install motor to compressor and check vibration*

8. Services Performed  
*Installed motor to compressor. The motor did not come back with the heater box or heaters in it. The holes are filled in with varnish. We decided to reschedule the finish of the job until Darren can come and remove his lock and check the fuses so that we don't single phase the motor on startup.*




Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



*This pic is of an identical motor with the heaters and box*



9. Service Technician Recommendations	
Remove lock, check fuses and have us come back to finish the startup.	
Approval Signatures	
10. Service Technician Signature	Trevor Hall
	
11. Customer Signature	Chris Green
