

LR Field Services

Prepared for Dassault Falcon Jet (11751)

3801 East 10th st.
Little rock AR 72203

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104459
FormID: 23738389

Dassault Falcon Jet (11751)

3801 East 10th st.
Little rock, AR 72203

Job Information

1. Hi-Speed Job Number
2. Asset Type
3. Make
4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives
Look at job for quote.

8. Services Performed
Fan end is FEU339 bearing. Pulley end is FU339. 2 7/16" shaft. Inspected job and took Vib readings to check motor as well. I would quote 8 hours to take apart, change bearings and reassemble plus bearings.



9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to be 'T. Hall', written in a cursive style.

11. Customer Signature

Phil Baldwin

A handwritten signature in black ink, appearing to be 'Phil Baldwin', written in a cursive style.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104459
FormID: 24267994

Dassault Falcon Jet (11751)
3801 East 10th st.
Little rock, AR 72203

Job Information

1. Hi-Speed Job Number	104459
2. Asset Type	Dust collector fan
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Dust collector MDP-6

Service Call Details

7. Service Objectives
To change out bearings on fan
8. Services Performed
Same as objective



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall



11. Customer Signature

Bailey A Allen

