# LR Field Services

Prepared for Entergy Transformer Shop (10004)

5001 Thibault Rd Little Rock AR 72206

## **Table of Contents**



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 104869 FormID: 25088677

## **Field Service Ticket**

**Entergy Transformer Shop (10004)** 

5001 Thibault Rd Little Rock, AR 72206

Job Information		
1.	Hi-Speed Job Number	104869
2.	Asset Type	Paint booth
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	

#### Service Call Details

- 7. Service Objectives
  - To check squalling of fan belts
- 8. Services Performed

Belts are Static Safe 2700 3JJet. 3 belts each. 6 belts total. I checked the exhaust fan belts and they were very loose. One fans belt tightening nut had backed off. I tightened both motors belts and the squalling went away. Belts looked good.

















9. Service Technician Recommendations

### **Approval Signatures**

10. Service Technician Signature

**Trevor Hall** 

11. Customer Signature

**Chuck Huggins** 

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

(Mr /00)