LR Field Services

Prepared for Evergreen Packaging (10150)

Paper Mill Pine Bluff AR 71601

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





Field Service Ticket

Evergreen Packaging (10150)

Paper Mill Pine Bluff, AR 71601 FolderID: 104710 FormID: 24762613

Job Information		
1.	Hi-Speed Job Number	104710
2.	Asset Type	Multiple fans
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	

Service Call Details

- 7. Service Objectives
- 8. Services Performed

Balanced two fans and the customer is going to fix the third fan base and tighten the motor belts before next outage for me to balance when I come back. Third fan could not get to a stable speed because of the belts.



3B PV Supply



3B finish



3B start



ЗВ



2 Mach fan



2 Mach fan is good



2PM Bel Bond



2PM Bel Bond



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Jeremy Smith