

# LR Field Services

Prepared for Evonik(10512)

10300 Arch St. Pike  
Little Rock AR 72206

# Table of Contents

Field Service Ticket

1.0

---

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 02/05/2025

Powered by [INSPECTALL](#)

*Table of Contents*



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104097  
FormID: 23283572

Evonik(10512)

10300 Arch St. Pike  
Little Rock, AR 72206

### Job Information

- |                        |                    |
|------------------------|--------------------|
| 1. Hi-Speed Job Number | 104097             |
| 2. Asset Type          | Dust collector fan |
| 3. Make                |                    |



- |                                 |                            |
|---------------------------------|----------------------------|
| 4. Model                        |                            |
| 5. Serial Number                |                            |
| 6. Customer Asset ID/Asset Name | Outside dust collector fan |

### Service Call Details

7. Service Objectives  
*To take readings of motor and fan bearings.*

8. Services Performed  
*When I got on site we started the motor and I heard some slapping from the belts against the guard. We ended up loosening the motor and tightening the belts. We ran again and the motor sounded good and the belts quit slapping. The motor pulley is worn out and needs to be replaced. I took vibration readings on the motor and fan and everything seems to be good.*



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Service Technician Recommendations

*Replace motor pulley.*

**Approval Signatures**

10. Service Technician Signature

**Trevor Hall**



11. Customer Signature

**Teddy**

