LR Field Services

Prepared for Evonik(10512)

10300 Arch St. Pike Little Rock AR 72206

Table of Contents

Field Service Ticket

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

1.0

2.0



Field Service Ticket

Evonik(10512) 10300 Arch St. Pike

Little Rock, AR 72206

Job Information					
1.	Hi-Speed Job Number			104409	
2.	Asset Type				
3.	Make				
4.	Model				
5.	Serial Number				
6.	Customer Asset ID/Asse	t Name		fan 1306	
Service Call Details					
7.	Service Objectives				
	Balance fan				
8.	Services Performed	Select Measurement Point Acquire Trim Ron Date REINDER - May 15 EMBA BY ANN 15 EM			
has a lo	fan the upper bearing t of play in it and the fan ng around.		Zone 7 fan the upper bearing cannot tighten on the shaft and the shaft is wollered out inside the bearing. Fan is rocking.	Zone 7 upper bearing.	

FolderID: 104409 FormID: 23991050

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Zone 6 fan. Lower bearing is not Zone 8 fan is good. Has a little Preheat blower set to the shaft and shaft is resonance in the base. spinning inside it.

Preheat blower shows to be in balance.





Baghouse fan

Baghouse fan is good

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

11. Customer Signature

1mm

Tim Wozny

Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Field Service Ticket

Evonik(10512) 10300 Arch St. Pike Little Rock, AR 72206 FolderID: 104409 FormID: 23991103

Job Information				
1.	Hi-Speed Job Number			
2.	Asset Type			
3.	Make			
4.	Model			
5.	Serial Number			
6.	Customer Asset ID/Asset Name			
Service Call Details				
7.	Service Objectives			
8.	Services Performed			
9.	Service Technician Recommendations			
Approval Signatures				
10.	Service Technician Signature			
11.	Customer Signature			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.