# LR Field Services

Prepared for Evonik(10512)

10300 Arch St. Pike Little Rock AR 72206

## **Table of Contents**

Field Service Ticket	1.0
Field Service Ticket	2.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





## **Field Service Ticket**

Evonik(10512) 10300 Arch St. Pike Little Rock, AR 72206 FolderID: 104409 FormID: 23991050

#### **Job Information**

1. Hi-Speed Job Number 104409

2. Asset Type



- Make
- 4. Model
- 5. Serial Number
- 6. Customer Asset ID/Asset Name fan 1306

#### **Service Call Details**

Service Objectives
Balance fan. Initial on 1306 fan 0.9 left 3.4 right.final left 0.5 right 2.4

8. Services Performed



Zone 5 fan the upper bearing has a lot of play in it and the fan is rocking around.







Zone 7 fan the upper bearing cannot tighten on the shaft and the shaft is wollered out inside the bearing. Fan is rocking.





Zone 7 upper bearing.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Zone 6 fan. Lower bearing is not Zone 8 fan is good. Has a little set to the shaft and shaft is resonance in the base. spinning inside it.

Preheat blower

Preheat blower shows to be in balance.





Baghouse fan

Baghouse fan is good

9. Service Technician Recommendations

1~ M

#### **Approval Signatures**

10. Service Technician Signature

**Trevor Hall** 

11. Customer Signature

**Tim Wozny** 

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 104409 FormID: 23991103

## **Field Service Ticket**

Evonik(10512) 10300 Arch St. Pike Little Rock, AR 72206

Job In	formation
1.	Hi-Speed Job Number
2.	Asset Type
3.	Make
4.	Model
5.	Serial Number
6.	Customer Asset ID/Asset Name
Service Call Details	
7.	Service Objectives
8.	Services Performed
9.	Service Technician Recommendations
Approval Signatures	
10.	Service Technician Signature
11.	Customer Signature