

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 103949 FormID: 22987249

> > P6

Field Service Ticket

Mechanisms- Weyerhaeuser (12590-101 E Columbia Road 14

Emerson, AR 71740

| Job In | formation | | Ō |
|--------|---------------------|--------|------|
| 1. | Hi-Speed Job Number | 103 | 3949 |
| 2. | Asset Type | hammer | mill |
| 3. | Make | | |
| 4. | Model | | P4 |
| | | | |



6. Customer Asset ID/Asset Name



Service Call Details o

Service Objectives

Balance hammer mill at or below 1.0 mil

8. Services Performed

Р8

Initial reading 1.7 mils on left plane and 1.3 mils on right plane. Final reading 0.9 mils on left plane and 0.8 mils on right plane.





Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

| 9. Service Technician Recommendations | | | | |
|---------------------------------------|-------------|--|--|--|
| Approval Signatures | | | | |
| 10. Service Technician Signature | Shon Jones | | | |
| 11. Customer Signature | Evan Parker | | | |
| Evan Parker | | | | |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.