



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103974  
FormID: 23086899

Potlatch-Ola  
729 Hwy 10 East  
Ola, AR 72853

### Job Information

- |                                 |        |
|---------------------------------|--------|
| 1. Hi-Speed Job Number          | 103974 |
| 2. Asset Type                   | hog    |
| 3. Make                         |        |
| 4. Model                        |        |
| 5. Serial Number                |        |
| 6. Customer Asset ID/Asset Name |        |

### Service Call Details



- |   |    |
|---|----|
| 7. Service Objectives   |    |
| <i>Balance hog after drive end bearing change</i>   |    |
| 8. Services Performed   |    |
| <i>After getting bearing cut off shaft damage was significant and customer decided to pull the unit for repair.</i> |    |
| 9. Service Technician Recommendations   | P9 |



### Approval Signatures

- |                                  |               |
|----------------------------------|---------------|
| 10. Service Technician Signature | Shon Jones    |
| 11. Customer Signature           | Robert Hilton |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.