



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104230
FormID: 23614549

Mondi Bags USA, LLC
3501 Jefferson Pkway
Pine Bluff, AR 71602

Job Information



- | | |
|------------------------|----------|
| 1. Hi-Speed Job Number | 104230 |
| 2. Asset Type | DC motor |
| 3. Make | P3 |



- | |
|---------------------------------|
| 4. Model |
| 5. Serial Number |
| 6. Customer Asset ID/Asset Name |

Service Call Details



- | |
|-----------------------|
| 7. Service Objectives |
|-----------------------|
- To check dc motor.*

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

8. Services Performed

P8

Fields have 154 ohms. Fields Meg 2000 megaohms, armature, brush rack and interpoles have 2000 megaohms. Overload has 0.4 ohms. Brushes look good. Inside of motor looks good and commutator has a good carbon film on it. I couldn't find any problems with the motor. The leads going to the motor have 2000 megaohms on one and 330 megaohms on the other. The cabinet has caught fire below the drive at some point and has multiple burnt wires. Motor runs but they are having a control wiring problem stopping the rolls in the machine.



9. Service Technician Recommendations

Have an electrician look at the wiring inside the panel.

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Gerald Lewis

A handwritten signature in black ink, appearing to read "Gerald Lewis", is written within a rectangular box.