



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104197  
FormID: 23637644

**Midsouth Steam Boiler**  
3805 Pointer Trail East  
Van Buren, AR 72956

### Job Information




- |                        |                   |    |
|------------------------|-------------------|----|
| 1. Hi-Speed Job Number | 104197            |    |
| 2. Asset Type          | boiler blower fan |    |
| 3. Make                |                   | P3 |



- |          |  |    |
|----------|--|----|
| 4. Model |  | P4 |
|----------|--|----|



- |                  |  |    |
|------------------|--|----|
| 5. Serial Number |  | P5 |
|------------------|--|----|



- |                                 |             |    |
|---------------------------------|-------------|----|
| 6. Customer Asset ID/Asset Name | 1200 boiler | P6 |
|---------------------------------|-------------|----|



### Service Call Details



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

7. Service Objectives

P7

*Check vibration on boiler to see if unbalanced*



8. Services Performed

*Vibration readings o boiler saved. Check fan shaft and motor shaft for end play, none present.*

9. Service Technician Recommendations

*When fan cycles air surging noise can be heard. Unsafe to put probe directly on fan opposite pulley side bearing.*

**Approval Signatures**

10. Service Technician Signature

11. Customer Signature

**Lonel Jackson**

