



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104176  
FormID: 23482028

Arkansas Lime Company  
600 Limesdale Rd  
Batesville, AR 72501

### Job Information

- |                                 |               |
|---------------------------------|---------------|
| 1. Hi-Speed Job Number          | 104176        |
| 2. Asset Type                   | fan and motor |
| 3. Make                         |               |
| 4. Model                        |               |
| 5. Serial Number                |               |
| 6. Customer Asset ID/Asset Name | ID fan        |

### Service Call Details



7. Service Objectives  
*To align pulleys with belt laser*

8. Services Performed  
*We straightened the pulleys and fan shaft out to line up with the motor, locked down the new taper lock bearings on the shaft and then I showed the contractors that were helping how to adjust the bearing to be an expansion bearing. We put the belts on and test ran the fan.*

P8



9. Service Technician Recommendations  
*Motor needs to be tightened up some to tighten the belts.*

### Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Service Technician Signature

**Trevor Hall**

A handwritten signature in black ink, appearing to read 'T. Hall', is written over a light gray background.

11. Customer Signature

**Customer Said To Send The  
Invoice**