



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104216  
FormID: 23578590

**Bryce Corporation (10053-BRC)**  
450 S. Benton  
Searcy, AR 72143

### Job Information

- |                                 |             |
|---------------------------------|-------------|
| 1. Hi-Speed Job Number          | 104216      |
| 2. Asset Type                   | Recycle fan |
| 3. Make                         |             |
| 4. Model                        |             |
| 5. Serial Number                |             |
| 6. Customer Asset ID/Asset Name | Trim fan    |

### Service Call Details



7. Service Objectives

*To balance fan.*

8. Services Performed

P8

*Upon inspection I found four broken fan blades. I used a rosebud torch to heat the blades and reshape them back to normal. I then welded the blades back solid so I could begin to balance the fan. The fan started at around 30 mils at 3000 rpm and I got it down to 0.19 on the fan end and 1.2 on the pulley end. The shaft is still bent roughly 0.020" on the fan end bearing.*



9. Service Technician Recommendations

*Replace fan and shaft once we get the spare at our shop done and returned.*

### Approval Signatures

- |                                  |             |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Ryan Pratt

