

## **Field Service Ticket**

FolderID: 103997 FormID: 23083077

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011

Job Information		
1.	Hi-Speed Job Number	103997
2.	Asset Type	Ball mill motor
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	#9 ball mill
Service Call Details		
7.	Service Objectives	
	To laser align motor to gearbox	
8.	Services Performed     P8       Tried to align motor to gearbox. I could not get my lasers to work properly but the unit was straight edged.     Both shafts were true with a dial indicator and shafts were not touching.     P8	
		BEE PHASE EEDUTY MOTOR EEELS EXESS   Marcon EXESS   Marcon Marcon   Marcon Design   Marcon Design
9. Service Technician Recommendations		
Approval Signatures		
10.	Service Technician Signature	Trevor Hall
11.	Customer Signature	David Wolfe

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.