



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

CT POLYMERS LLC  
1601 HASTINGS  
SEARCY, AR 72143

FolderID: 104599  
FormID: 24458477

### Job Information

1. Hi-Speed Job Number	104599
2. Asset Type	gearbox
3. Make	Erema
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

### Service Call Details



#### 7. Service Objectives

P7



#### 8. Services Performed

*Visual inspection on gear shaft where seal rides.*

#### 9. Service Technician Recommendations

*Try to locate seal on shaft that is offset from grooving if possible. Shaft has deep grooves and for long term fix shaft needs repaired or replaced.*

### Approval Signatures

#### 10. Service Technician Signature

Shon Jones

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11. Customer Signature

**Robert Banks**

A handwritten signature in black ink, appearing to read "Robert Banks", written in a cursive style.