## LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff AR 71602

## Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



FolderID: 104564

FormID: 24367047

## **Field Service Ticket**

Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff, AR 71602

Job Information		
1.	Hi-Speed Job Number	104564
2.	Asset Type	Hammer mill
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	Dry hammer mill 2
Service Call Details		
7.	Service Objectives	

- To balance hammer mill
- 8. Services Performed

Balanced hammer mill to the best that I could. The drive end shaft is bent 30 thousandths. Customer is reading a 0.12 inches per second on their end. I am showing 1.2 and 0.47 mils. Customer was glad to get the vibration down. I started out at 3.89 and 1.29.









9. Service Technician Recommendations Replace shaft as soon as possible.

## **Approval Signatures**

10. Service Technician Signature

**Trevor Hall** 

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Trell

11. Customer Signature

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Seth Garrison