LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff AR 71602

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 105013 FormID: 25506520

Field Service Ticket

Highland Pellets (012194) 5601 Industrial Dr North Pine Bluff, AR 71602

Job Information			
1.	Hi-Speed Job Number	105013	
2.	Asset Type	quarterly vibration	
3.	Make		
4.	Model		
5.	Serial Number		
6.	Customer Asset ID/Asset Name		

Service Call Details

- 7. Service Objectives

 Collect vibration data for analysis
- 8. Services Performed
- 9. Service Technician Recommendations

 Missing bolts on fa cover line 3 motor 2 pellet press motor





Approval Signatures

10.	. Service Technician Signature	Shon Jones	
11.	. Customer Signature	Jerry	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 08/15/2025 Powered by INSPECTALL 1.0