

LR Field Services

Prepared for Johnson Controls Inc

4301 WEST MARKAM
Little Rock AR 72204

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 04/10/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Johnson Controls Inc
4301 WEST MARKAM
Little Rock, AR 72204

FolderID: 104425
FormID: 24055729

Job Information

1. Hi-Speed Job Number **104425**

2. Asset Type



3. Make



4. Model



5. Serial Number

6. Customer Asset ID/Asset Name



Service Call Details

7. Service Objectives

Test motor that had fuses blown.





Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



8. Services Performed

Merger, resistance, and surge test.



9. Service Technician Recommendations

Check cabling between motor and switch gear.

Approval Signatures

10. Service Technician Signature

Shon Jones

11. Customer Signature

Adam Hoover