

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104144
FormID: 23384035

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

- | | |
|------------------------|---------------|
| 1. Hi-Speed Job Number | 104144 |
| 2. Asset Type | Fan |
| 3. Make | |



- | | |
|---------------------------------|---------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Stripper fan |



Service Call Details

- | | |
|-----------------------|---|
| 7. Service Objectives | <i>To balance fan</i> |
| 8. Services Performed | <i>Balanced fan from 2.5 mils down to 0.05 and 0.6.</i> |



- | | |
|---------------------------------------|--|
| 9. Service Technician Recommendations | |
|---------------------------------------|--|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

The accelerometer needs to be taken off of the fan shroud and be placed directly on the motor so it isn't reading resonance from the frame and air flow.



Approval Signatures

10. Service Technician Signature

Trevor Hall

Handwritten signature of Trevor Hall.

11. Customer Signature

Neil Little

Handwritten signature of Neil Little.