LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr. Maumelle AR 72113

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





Field Service Ticket

Kimberly Clark (10176-KCM) 500 Murphy Dr. Maumelle, AR 72113 FolderID: 104577 FormID: 25157812

Job Information		
1.	Hi-Speed Job Number	104577
2.	Asset Type	PDMA testing on C3
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	
5.	Serial Number	

Service Call Details

- 7. Service Objectives
- 8. Services Performed



Picker 1



Picker 1 before



Picker 1 after



BWE 1 before



BWE 1



BWE1 after



BWE 1



Extruded 1 before



Extruded 1 after



Extruded 2



Extruded 2 before



Extruded 2 after

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



BWE 2



BWE 2 before



BWE 2 after



Picker 2



Picker 2 before



Picker 2 after



Picker 3



Picker 3 before



Picker 3 after



BWE 3



BWE 3 before



BWE 3 after



Extruder 3



Extruder 3 before



Extruder 3 after

Service Technician Recommendations Vacuum out disconnect panels



Disconnect picket 2



Disconnect picker 2



Disconnect picker 2



Picker 1 disconnect







Picker 1 disconnect

Picker 1 disconnect

Picker 1 after clean disconnect

Approval Signatures

10. Service Technician Signature

11. Customer Signature