

7030 Ryburn Dr. Millington, TN

Phone: (901) 873-5300

Fax: (901) 873-5301

www.gohispeed.com


February 3, 2025

Seth McMillan Lanxess Memphis Plant


Seth,


The following is a summary report of the refrigeration compressors. This report contains waterfall spectra and waveform data for each point and contains all data taken for both machines. Each spectrum and waveform should have a time stamp next to the data. Please let us know if there are any questions or comments.

## **COMPRESSOR A**












































































































































































































## Piping at Bottom Side of Compressor DISCHARGE (off route point) Vertical position




Note that we only have one set of data for these points.

## Compressor B







## oxone.rbm / OXON / REFRIGERATION COMPRESSOR B / MOH - MOTOR OUTBOARD HORIZONTAL



















































#### oxone.rbm / OXON / REFRIGERATION COMPRESSOR B / MIA - MOTOR INBOARD AXIAL










































































































































# SUCTION (TOP) PIPE (in line with shaft)







### SUCTION (TOP) PIPE (perpendicular to shaft)



# DISCHARGE (BOTTOM) PIPING (in line with shaft)



**DISCHARGE (BOTTOM) PIPING (perpendicular with shaft)** 



# Abbreviated Last Measurement Summary

MEASUREMENT POINT	OVERALL LEVEL	HFD / VHFD
REFGCOMPA - REFRIGERATION	COMPRESSOR A (21	-Aug-24)
	OVERALL LEVEL	1-20 kHZ
MOH	.067 In/Sec	.477 G-s
MOV	.045 In/Sec	.261 G-s
MOA	.029 In/Sec	.141 G-s
MIH	.055 In/Sec	.781 G-s
MIV	.032 In/Sec	.180 G-s
MIA	.029 In/Sec	.188 G-s
C1H	.034 In/Sec	.297 G-s
C1V	.027 In/Sec	.140 G-s
C1A	.052 In/Sec	.209 G-s
C2H	.039 In/Sec	.580 G-s
C2V	.319 In/Sec	.168 G-s
C2A	.104 In/Sec	.125 G-s
СЗН	.065 In/Sec	.396 G-s
C3V	.288 In/Sec	.234 G-s
C3A	.127 In/Sec	.250 G-s
C4H	.052 In/Sec	.849 G-s
C4V	.065 In/Sec	.178 G-s
C4A	.166 In/Sec	.205 G-s
* P9	.615 In/Sec	.145 G-s
* P10	1.508 In/Sec	.107 G-s

REFGCOMPB - REFRIGER	RATION COMPRESSOR B (13	-Dec-24)
	OVERALL LEVEL	1-20 kHZ
MOH	.084 In/Sec	.355 G-s
MOV	.055 In/Sec	.146 G-s
MOA	.030 In/Sec	.102 G-s
MIH	.062 In/Sec	.294 G-s
MIV	.034 In/Sec	.060 G-s
MIA	.035 In/Sec	.109 G-s
C1H	.058 In/Sec	.452 G-s
C1V	.283 In/Sec	.194 G-s
C1A	.050 In/Sec	.159 G-s
C2H	.087 In/Sec	.944 G-s
C2V	.271 In/Sec	.109 G-s
C2A	.075 In/Sec	.254 G-s
СЗН	.053 In/Sec	.376 G-s
C3V	.159 In/Sec	.187 G-s
C3A	.070 In/Sec	.152 G-s
C4H	.039 In/Sec	.817 G-s
C4V	.455 In/Sec	.135 G-s
C4A	.079 In/Sec	.205 G-s
<b>P</b> 7	.849 In/Sec	.464 G-s
P8	.464 In/Sec	.374 G-s
P9	.793 In/Sec	.598 G-s
P10	.430 In/Sec	1.523 G-s

\_\_\_\_\_\_

Clarification Of Vibration Units:

Acc --> G-s PK Vel --> In/Sec PK

As always, it has been a pleasure to serve your Lanxess. If there are any comments or questions, do not hesitate to contact us.

Sincerely,

ISO Certified Vibration Analyst, Category III

Kevin W. Mozewell



QualiTest<sub>®</sub> Diagnostics

Cell: 901-486-4565

Email: <a href="mailto:kwilliam@gohispeed.com">kwilliam@gohispeed.com</a>

*Hi-Speed* Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

<sup>\* -</sup> Indicates Data Has Date/Time Different From Machine Date/Time