

ML Field Service

Prepared for MC Ionic Solutions (004136)

2665 Fite Road
Memphis TN 38127

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/22/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 155636
FormID: 24528782

MC Ionic Solutions (004136)

2665 Fite Road
Memphis, TN 38127

Job Information

- | | |
|------------------------|-------------|
| 1. Hi-Speed Job Number | 155636 |
| 2. Asset Type | recycle fan |
| 3. Make | |



- | | |
|---------------------------------|------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | East recycle fan |


Service Call Details

- | |
|---|
| 7. Service Objectives |
| <i>Check vibration and analyze.</i> |
| 8. Services Performed |
| <i>Vibration analysis</i> |
| 9. Service Technician Recommendations |
| <i>Peak vibration coming from the motor. 0.9 in/sec overall. Appears to be looseness on the drive end of motor either in the bearing housing or on the shaft journal. Fan bearings are under 0.2 in/sec. Customer was made aware that field balance could help bring down some vibration but is unlikely to change motor vibration. Because of their process needs they opted to schedule motor change next week then call for balance if needed.</i> |

Approval Signatures

- | | |
|----------------------------------|------------|
| 10. Service Technician Signature | Shon Jones |
|----------------------------------|------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Michael Taylor

