

LR Field Services

Prepared for NABCO Service Company

PO Box 1547
Conway AR 72033

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/21/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104308
FormID: 23820367

NABCO Service Company
PO Box 1547
Conway, AR 72033

Job Information

- | | |
|------------------------|--------------------|
| 1. Hi-Speed Job Number | 104308 |
| 2. Asset Type | Glycol pump |



3. Make



- | | |
|---------------------------------|----------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Glycol pump 4 |

Service Call Details

7. Service Objectives
To align new motor and pump system.
8. Services Performed
Aligned motor to pump. Started at -60 on the verticle offset and -120 on the horizontal offset. Ended at 0.2 and 0.3.



Finish

9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to be 'T. Hall', written in a cursive style.

11. Customer Signature

Craig Bryan

A handwritten signature in black ink, appearing to be 'C. Bryan', written in a cursive style.