

LR Field Services

Prepared for NEWTERRA HEBER SPRINGS

250 BOLTON SULLIVAN DRIVE
HEBER SPRING AR 72543

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/09/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

NEWTERRA HEBER SPRINGS
250 BOLTON SULLIVAN DRIVE
HEBER SPRING, AR 72543

FolderID: 104548
FormID: 24398652

Job Information

1. Hi-Speed Job Number

104548

2. Asset Type

exhaust fan



3. Make



4. Model

5. Serial Number

6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives

Check fan vibration after bearing change and fan cleaning.

8. Services Performed

Collect vibration data for analysis and balance if needed.

9. Service Technician Recommendations

Vibration on fan is well within tolerance. Report on file.

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures

10. Service Technician Signature

Shon Jones

A handwritten signature in black ink, appearing to be 'Shon Jones', written over a light blue background.

11. Customer Signature

Walker stormont

A handwritten signature in black ink, appearing to be 'Walker stormont', written over a light blue background.