

LR Field Services

Prepared for Peco Foods

625 S. Allen Street
Batesville AR 72501

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/08/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104203
FormID: 23645036

Peco Foods

625 S. Allen Street
Batesville, AR 72501

Job Information

1. Hi-Speed Job Number	104203
2. Asset Type	Ammonia compressor
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Compressor


Service Call Details

7. Service Objectives

To check motor and possible remove motor and soft start.

8. Services Performed

We inspected the motor and instantly seen copper balls laying in the bottom of the motor on both sides. Motor was disconnected upon arrival from soft start. We removed the motor and the electrician removed the soft start. We loaded them up in the van and brought back to the shop.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/08/2025

Powered by [INSPECTALL](#)

1.0



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Michel Beyerle