LR Field Services

Prepared for PECO FOODS NEWARK

318 SOUTH LOCUST STREET NEWARK AR 72562

Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



FolderID: 104539

FormID: 24377959

Field Service Ticket

PECO FOODS NEWARK

318 SOUTH LOCUST STREET NEWARK, AR 72562

ob In	formation	
1.	Hi-Speed Job Number	104539
2.	Asset Type	Hammer Mill
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	Hammer mill 2
ervic	e Call Details	
7.	Service Objectives	
	To balance hammer mill	
8.	Services Performed	
	Balanced hammer mill from 10 mils down to 1 and 2 mils. Hammer mill had a lot of metal go through it.	
	Start	
9.	Service Technician Recommendations	
ppro	val Signatures	
	Service Technician Signature	Trevor Hall
11.	Customer Signature	Ron

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.