LR Field Services

Prepared for Planters Cotton Oil Mill

2901 Planters Drive Pine Bluff AR 71601

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 105020 FormID: 25463200

Field Service Ticket

Planters Cotton Oil Mill 2901 Planters Drive Pine Bluff, AR 71601

Job Information

- 1. Hi-Speed Job Number 105020
- 2. Asset Type Clutch
- 3. Make



- 4. Model
- 5. Serial Number
- Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives

To assist with troubleshooting the clutch

8. Services Performed

I inspected the old clutches to see how they work and the customer had me wait in the maintenance shop while I was doing so. The customer then came and got me to tell me that he fixed it by tightening up the torque spring. Customer said he wanted someone there just in case he couldn't figure it out. He then had me bring back three clutches to inspect and repair.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Michael Cox

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.