

LR Field Services

Prepared for Riceland Foods-Hazen (10247-09)

1101 Riceland Street
Hazen AR 72160

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0




Hi-Speed Industrial Service
 7030 Ryburn Dr
 Millington, Tn 38053
 901-873-5300

Field Service Ticket

FolderID: 104283
 FormID: 23742273

Riceland Foods-Hazen (10247-09)
 1101 Riceland Street
 Hazen, AR 72160

Performed By: Shon Jones
Date Completed: 03/14/2025

Job Information	
1. Hi-Speed Job Number	104283
2. Asset Type	dust collector fan
3. Make	
<div style="display: flex; justify-content: space-around;">    </div>	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	west bag house fan
Service Call Details	
7. Service Objectives	<i>Clean accumulated build up on fan and balance</i>
8. Services Performed	<i>Initial readings 8.4 and 2.7 mils. Final reading 0.5 and 0.6 mils</i>
<div style="display: flex; justify-content: space-around;">   </div>	
<i>Initial</i>	<i>Final</i>
9. Service Technician Recommendations	
Approval Signatures	
10. Service Technician Signature	Shon Jones

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Shane Weems





Field Service Ticket

FolderID: 104283
 FormID: 23742272

Riceland Foods-Hazen (10247-09)
 1101 Riceland Street
 Hazen, AR 72160

Performed By: Shon Jones
Date Completed: 03/14/2025

Job Information

1. Hi-Speed Job Number	104283
2. Asset Type	dust collector fan
<div style="display: flex; justify-content: space-around;">   </div>	
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	middle bag house fan

Service Call Details

7. Service Objectives	
<i>Clean accumulated dirt off of fan and balance</i>	
	
8. Services Performed	
<i>Initial readings showed 18.1 and 10.9 mils out of balance.</i>	
<i>Final readings showed 0.9 and 0.7 mils.</i>	
<div style="display: flex; justify-content: space-around;">   </div>	
<i>Initial</i>	<i>Final</i>

9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures

10. Service Technician Signature

Shon Jones

A handwritten signature in black ink, appearing to be 'Shon Jones', written in a cursive style.

11. Customer Signature

Shane Weems

A handwritten signature in black ink, appearing to be 'Shane Weems', written in a cursive style.