LR Field Services

Prepared for Riceland Foods

1200 N Park Ave Stuttgart AR 72160

Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



FolderID: 104671

FormID: 24610151

Field Service Ticket

Riceland Foods 1200 N Park Ave

Stuttgart, AR 72160

Job In	formation	
1.	Hi-Speed Job Number	104671
2.	Asset Type	
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	
Servic	e Call Details	
7.	Service Objectives	
	Collect vibration data for monthly analysis.	
8.	Services Performed	
	Walk through plant and collect data.	
9.	Service Technician Recommendations	
	Broken motor base.crack on drive end left side by mounting bolt. high vibration seen in the vertical plane on motor. Replace motor adapter base.	
	val Signatures	
10.	Service Technician Signature	Shon Jones
4	Imp	
11.	Customer Signature	Donovan Gilmore
	VC/	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.