

LR Field Services

Prepared for RIVIANA FOODS INC

400 WEST MAIN STREET
CARLISLE AR 72024

Table of Contents

Field Service Ticket - <i>LR MOTOR SHOP</i>	1.0
Balancing Report - <i>LR MOTOR SHOP</i>	2.0
Field Service Ticket - <i>LR MOTOR SHOP</i>	3.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104316
FormID: 23794217

RIVIANA FOODS INC
400 WEST MAIN STREET
CARLISLE, AR 72024
LR MOTOR SHOP



Job Information

1. Hi-Speed Job Number	104316
2. Asset Type	fan
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Dryer fan #2

Service Call Details

7. Service Objectives <i>Balance fan</i>
8. Services Performed <i>Attempted fan balance. Found bearings to be bad. Customer intends to replace bearings and reschedule balance for 3/21/25</i>
9. Service Technician Recommendations <i>Replace bearings</i>

Approval Signatures

10. Service Technician Signature	David Maclin
	
11. Customer Signature	
	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Balancing Report

FolderID: 104316
FormID: 23794836

RIVIANA FOODS INC
400 WEST MAIN STREET
CARLISLE, AR 72024
LR MOTOR SHOP

General


1. Job Number
2. Report Date
3. Customer

Balancing Report

4. Balance Type
5. Balance Operating Speed
6. Starting Measurements

Left End

Right End



7. Balancing Specification
8. Finished Measurements

Left End

Right End

9. List Parts Needed
10. Service Technician

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104316
FormID: 23828808

RIVIANA FOODS INC
400 WEST MAIN STREET
CARLISLE, AR 72024
LR MOTOR SHOP

Job Information

- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 104316 |
| 2. Asset Type | Dryer fan |
| 3. Make | |



- | | |
|---------------------------------|-------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Dryer 2 fan |

Service Call Details

- | | |
|-----------------------|---|
| 7. Service Objectives | To balance fan |
| 8. Services Performed | Started at over 7 mils. Ended at 0.4 and 0.3. |



Finish

Start

- | | |
|---------------------------------------|--|
| 9. Service Technician Recommendations | |
|---------------------------------------|--|

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- | | |
|------------------------|--------------|
| 11. Customer Signature | Tracey Smith |
|------------------------|--------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

A handwritten signature in black ink, appearing to be 'TJL', is located in the top left corner of the page.