

# LR Field Services

Prepared for Rogers Group (01189502)

1032 Hwy 5  
Cabot AR 72023

# Table of Contents

Field Service Ticket

1.0

---

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 06/05/2025

Powered by [INSPECTALL](#)

*Table of Contents*



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104718  
FormID: 24697714

### Rogers Group (01189502)

1032 Hwy 5  
Cabot, AR 72023

#### Job Information

1. Hi-Speed Job Number	104718
2. Asset Type	250 hp motor and fan
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	ID fan


#### Service Call Details

##### 7. Service Objectives

*To remove motor, fan bearings and coupling. Reinstall new bearings and coupling, laser align motor to fan and then balance.*

##### 8. Services Performed

*Same as objective*



##### 9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

## Approval Signatures

10. Service Technician Signature

**Trevor Hall**

A stylized, handwritten signature in black ink, appearing to be 'T. Hall'.

11. Customer Signature

**Marcus Andrews**

A handwritten signature in black ink, appearing to be 'Marcus Andrews'.