

LR Field Services

Prepared for SSC Services for Education (12860)

871 N 10th Street
Arkadelphia AR 71923

Table of Contents













Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104807
FormID: 24953477

SSC Services for Education (12860)
871 N 10th Street
Arkadelphia, AR 71923

Job Information			
1. Hi-Speed Job Number			104807
2. Asset Type			
			
			
			Motor nameplate
3. Make			
			
4. Model			
			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

5.	Serial Number	
6.	Customer Asset ID/Asset Name	cooling tower 1 and 2
Service Call Details		
7.	Service Objectives	
	<i>Check vibration on 2 cooling towers</i>	
8.	Services Performed	
9.	Service Technician Recommendations	
	<i>Use factory recommended belts. Belts sitting too deep in groove and appear to be too narrow. Belts are slipping. Knock out vibration switch has been in service for approximately 10 years and has become weak. Motors have been in service approximately 10 years and bearings are bad.</i>	
Approval Signatures		
10.	Service Technician Signature	Shon Jones
11.	Customer Signature	Michael Howard