

LR Field Services

Prepared for Union Pacific-Vine St 10945

1020 N. Vine Street
North Little Rock AR

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/06/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104551
FormID: 24347567



Union Pacific-Vine St 10945
1020 N. Vine Street
North Little Rock, AR

Job Information

1. Hi-Speed Job Number	104551
2. Asset Type	Railroad river bridge
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives
<i>To check DC motors for locomotive river bridge.</i>
8. Services Performed
<i>Armature, brush rack, interpoles and leads on South drive motor have 100 megaohms. Ohms are 93.5 on the fields. Fields have 521 megaohms. Armature, brush rack, interpoles and leads on the North drive motor have 88 megaohms. Ohms are 91.5 on the fields. Fields have 90 megaohms. We found a jumper that was not set properly on the S14 terminal for the field current on the North drive. Jumper numbers 5 and 6 needed to be in the ON position. 5 was Off. After changing the jumper position the amperage on the system are even with each other. Bridge goes up and down as it is supposed to.</i>



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/06/2025

Powered by [INSPECTALL](#)

1.0





9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read "Trevor Hall", written over a light blue background.

11. Customer Signature

Joshua Fowler

A handwritten signature in black ink, appearing to read "Joshua Fowler", written over a light blue background.