

LR Field Services

Prepared for Welspun Tubular (11685)

9301 Frazier Pike
Little Rock AR 72206

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 08/12/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 105026
FormID: 25477100

Welspun Tubular (11685)

9301 Frazier Pike
Little Rock, AR 72206

Job Information

- | | |
|---------------------------------|-------------|
| 1. Hi-Speed Job Number | 105026 |
| 2. Asset Type | Stage pump. |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives

To check pump that locked up about a minute after startup.

8. Services Performed

Customer had the pump pulled upon arrival. I tried turning the shaft and it is very hard to turn. It feels like one of the sleeves may not have gotten proper lubrication up top or is too tight. I brought the pump back to the shop so we can do further evaluation. Customer was very polite about the situation.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

