

LR Field Services

Prepared for WESTERN FOODS LLC

5215 INDUSTRIAL DR,S
PINE BLUFF AR 71602

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 02/26/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104202
FormID: 23536048

WESTERN FOODS LLC
5215 INDUSTRIAL DR,S
PINE BLUFF, AR 71602

Job Information

- | | |
|---------------------------------|-------------------|
| 1. Hi-Speed Job Number | 104202 |
| 2. Asset Type | hammer mill motor |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Mill |


Service Call Details

7. Service Objectives

To check vibration coming from motor

8. Services Performed

PB022625 po number. Pulley was out of balance so we field balanced the pulley to bring motor vibration down. Motor and pulley started at over 2 mils



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Moises G

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

A handwritten signature in black ink, consisting of stylized, overlapping loops and strokes, located in the top left corner of the page.