

LR Field Services

Prepared for West Fraser Mills (10728-01)

1400 Main Street
Leola AR 72084

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/04/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104228
FormID: 23609533

West Fraser Mills (10728-01)

1400 Main Street
Leola, AR 72084

Job Information

- | | |
|---------------------------------|--------|
| 1. Hi-Speed Job Number | 104228 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives

Take readings on both tables and flappers.



8. Services Performed

Data is under extra blowers

Motor 1 is the roll we just balanced by the cat walk. I measured from left to right. Blower is the flapper wheel under blower 1. Flapper 1 turns faster than the second one. Flapper 2-under blower 3, I started on the right hand side, closest to the wall. Motor outboard horizontal is on the right hand side. Inboard is on the left. Last roll is under blower 4. Cannot get the first roll on the second belt (third roll) right hand side due to guarding. Third roll left hand side, closest to operator , is under blower 5.



Blower 2 motor. Can't get the other side closest to office because of guarding.



Flapper is under blower 3.

9. Service Technician Recommendations

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to be 'T-Hall', written over a horizontal line.

11. Customer Signature

James Parker

A handwritten signature in black ink, appearing to be 'J Parker', written over a horizontal line.