

Job Information

Job #:	139303				Date:	March 12, 2019
Priority:	-	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Southern Steel	Motor#:	139303

Name Plate Information

Kone crane	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	3250
MF11X-106N166P85 006E-	Model#:		Service Factor:	
	Rated RPM:	3600/600	Rated Voltage:	460
3	Rated Amps:	20/10	Cycles:	60
	MF11X-106N166P85 006E-	MF11X-106N166P85 Model#: 006E- Rated RPM:	(ODP) MF11X-106N166P85 Model#: 006E- Rated RPM: 3600/600	(ODP) MF11X-106N166P85 Model#: Service Factor: 006E- Rated RPM: 3600/600 Rated Voltage:

Special design: No

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassembly:	Good	Surge at reassem	bly: Good	Hi-pot reassembly: Good		
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phases C to A	Resistive imbalance		
Outgoing						
Test Run Inspection Date March 12, 2019						
Yes I have merged this motor and verified that all electrical tests are complete!						
Dower Supply						
Power Supply	Phas	se A	Phase B	Phase C		
No Load Voltage	460		460	460		
No Load Current	6		6	6		

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Test Run Inspection (Continued)

Ambient Temp:	71			
TIME	DE	Degree Change	ODE	Degree Change
START:	70	0	70	0
5 MIN:	71	1	71	1
10 MIN:	72	1	72	1
15 MIN:	73	1	73	1
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)		
	Horizontal	VDE	Axial
DE	0.021	0.026	0.016
ODE	0.020	0.024	0.014

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name: Micl

Michaeljordamn

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301