

Job Information

Job #: 140849 Date: October 7, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Runyun Motor#: 140849

Name Plate Information

Manufacturer: Notch American Enclosure: Totally Enclosed Horsepower/kW: 50

electric Fan Cooled

Serial#: 1409215300 Model#: PE326TS-50-2-EC Service Factor: 1.15

Frame: 326TS Rated RPM: 2930 Rated Voltage: 208-230/460

Phase: 3 Rated Amps: 117-110/55 Cycles: 60

Special design: No

Date

October 7, 2019



AC Electrical Inspection

Megs at reassembly:	Good	Surge at reassembly:	Good	Hi-pot reassembly:	Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Outgoing

Test Run Inspection

I have merged this motor and verified that all electrical tests are complete!

Power Supply

Phase A Phase B Phase C

No Load Voltage

No Load Current

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.



Test Run Inspection (Continued)

Ambient Temp:				
TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak (Readings should be less than .08 In/Sec Peak)

Horizontal VDE Axial

DE

ODE

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos







Yes, the shaft has been isolated for delivery.

Service Tech name: Stone Hubbard

Service Tech signature: