

Job Information

Job #:	94156				Date:	May 10, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Hormel		Motor#:

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	250hp
Serial#:		Model#:		Service Factor:	1.15
Frame:	447TY	Rated RPM:	3575	Rated Voltage:	460
Phase:	3	Rated Amps:	228	Cycles:	

Special design: Yes

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reasser	mbly: Good	Surge at reassem	ibly: Good	Hi-pot reassembly: Good			
Winding Resist	Winding Resistance Incoming						
	Phases A to B	Phases B to C	Phases C to	A Resistive imbalance			
Outgoing	15.513	15.189	15.430	1.6			
Test Run Inspection Date							
— I have merged this motor and verified that all electrical tests are complete!							
Power Supply Phase A Phase B Phase C							
No Load Voltage							
No Load Current							
Temperatures: (Degrees Fahrenheit)							
The formula of the sector of the state of th							

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR


Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)



Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Lynn McDonald

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301