

## **Job Information**

Job #:	95845				Date:	September 10, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

# **Customer Information**

Name: Lexicon Motor#:

## **Name Plate Information**

Manufacturer:	LEROY SOMER	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	22.2KW
Serial#:	736261D130012013	Model#:	23260549	Service Factor:	
Frame:	LS180LG-T	Rated RPM:	1760	Rated Voltage:	460
Phase:	3	Rated Amps:	35.7	Cycles:	60

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection**

Megs at reassem	bly: Good	Surge at reassembly:	Good	Hi-pot reassembly:	Good
Winding Resista	nce Incoming				
	Phases A to B	Phases B to C	Phases C to A	Resistive imbala	ince
Outgoing	0.00	0.00	0.00	0.00	

### **Test Run Inspection**

Date September 10, 2019

Yes I have merged this motor and verified that all electrical tests are complete!

#### **Power Supply**

	Phase A	Phase B	Phase C
No Load Voltage	459	457	457
No Load Current	9.3	9.3	8.9

### **Temperatures: (Degrees Fahrenheit)**

### Test run ball-bearing motors for 15 minutes.

### Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# MILLINGTON, TN LITTLE ROCK, AR

# **Test Run Inspection (Continued)**

#### Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



## **Test Run Inspection (Continued)**

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)		
	Horizontal	VDE	Axial
DE	0.007	0.034	0.009
ODE	0.050	0.042	0.013

#### Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

### **Additional photos**









Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301