

Job Information

Job #:	95885				Date:	September 6, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name: Delta Plastics Motor#:

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	250
Serial#:	S9142527-001002JR	Model#:		Service Factor:	1.0
Frame:	L3203	Rated RPM:	1765	Rated Voltage:	460
Phase:	3	Rated Amps:	295	Cycles:	60

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



AC Electrical Inspection

Megs at reassem	bly: Good	Surge at reassembly:	Good	Hi-pot reassembly: Good			
Winding Resistance Incoming							
	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance			
Outgoing	0.00	0.00	0.00	0.00			
Test Run I	nspection		Date	September 6, 2019			

Yes I have merged this motor and verified that all electrical tests are complete!

Power Supply

	Phase A	Phase B	Phase C
No Load Voltage	456	454	455
No Load Current	87.6	87.1	86.0

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANBAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be le	ess than .08 In/Sec Pea	k)
	Horizontal	VDE	Axial
DE	0.019	0.014	0.012
ODE	0.059	0.008	0.017

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254