

Job Information

Job #:	97168				Date:	August 12, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name: Wonder State Box Motor#:

Name Plate Information

460
60

Special design: No

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassem	oly: Good	Surge at reassembly:	Good	Hi-pot reassembly: Good		
Winding Resistance Incoming						
	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance		
Outgoing	0.00	0.00	0.00	0.00		
Test Run Inspection			Date	August 12, 2020		
Yes	I have merged this motor and verified that all electrical tests are complete!					

	Phase A	Phase B	Phase C
No Load Voltage	458	456	457
No Load Current	4.7	4.7	4.5

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Power Supply



MILLINGTON, TN LITTLE ROCK, AR


Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)



Total Motor End Float

Additional photos










Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301